

DANLERS


Your ref:
Our ref:
Date:

DANLERS Limited
Vinciens Road
CHIPPENHAM
Wiltshire SN14 6NQ
United Kingdom

Tel: +44 (0)1249 443377
Fax: +44 (0)1249 443388
E-mail: sales@danlers.co.uk
www.danlers.co.uk

Compliment Slips.indd/22

Product: 2-wire, plated, time lag switch.
Problem: Intermittent function.
Cause: Resistive load less than 40W (approx 100W inductive).
Solution: Wire a CAPLOAD power factor correction capacitor in parallel with load.



With Compliments

PIR OCCUPANCY SWITCHES • PHOTOCELLS • DAYLIGHT LINKED DIMMERS • REMOTE CONTROLS • TIME LAG SWITCHES • SECURITY SWITCHES • DIMMERS • HVAC CONTROLS • O.E.M. PRODUCTS

DANLERS


Your ref:
Our ref:
Date:

DANLERS Limited
Vinciens Road
CHIPPENHAM
Wiltshire SN14 6NQ
United Kingdom

Tel: +44 (0)1249 443377
Fax: +44 (0)1249 443388
E-mail: sales@danlers.co.uk
www.danlers.co.uk

Compliment Slips.indd/22

Product: 2-wire, plated, time lag switch.
Problem: Intermittent function.
Cause: Resistive load less than 40W (approx 100W inductive).
Solution: Wire a CAPLOAD power factor correction capacitor in parallel with load.



With Compliments

PIR OCCUPANCY SWITCHES • PHOTOCELLS • DAYLIGHT LINKED DIMMERS • REMOTE CONTROLS • TIME LAG SWITCHES • SECURITY SWITCHES • DIMMERS • HVAC CONTROLS • O.E.M. PRODUCTS

DANLERS


Your ref:
Our ref:
Date:

DANLERS Limited
Vinciens Road
CHIPPENHAM
Wiltshire SN14 6NQ
United Kingdom

Tel: +44 (0)1249 443377
Fax: +44 (0)1249 443388
E-mail: sales@danlers.co.uk
www.danlers.co.uk

Compliment Slips.indd/22

Product: 2-wire, plated, time lag switch.
Problem: Intermittent function.
Cause: Resistive load less than 40W (approx 100W inductive).
Solution: Wire a CAPLOAD power factor correction capacitor in parallel with load.



With Compliments

PIR OCCUPANCY SWITCHES • PHOTOCELLS • DAYLIGHT LINKED DIMMERS • REMOTE CONTROLS • TIME LAG SWITCHES • SECURITY SWITCHES • DIMMERS • HVAC CONTROLS • O.E.M. PRODUCTS